## Mintori Freestanding Contour Spa Bath [14 Jets]

Product Code: MI1800FSCNSPAWC



🗪 MADE IN AUSTRALIA





Spa shell

Pump, jets & fittings (refer to decina.com.au)

The Mintori has generous reclining lumbar supports, perfect for dual bathing and the classic oval design features a generous bath rim. Removable side panels, which use a patented magnetic fixing system, create access for easier installation & cleaning.

- AS/NZ Standard 2023/1995
- Adjustable self-supporting feet
- Removable side panels
- Steel rod reinforced rim
- Lumbar support
- Suitable for dual bathing
- 6 x flush C-Lenda™ centro jets 8 x flush C-Lenda™ mini jets
- 2 x flush C-Lenda™ air controls
- 1 x flush C-Lenda™ suction
- 1 x Sensa-Touch pad control (rim mounted)
- 750 watt 3-stage heat boost pump

## **PRODUCT SPECIFICATIONS**

Colour: High gloss white

Material: Premium sanitary grade acrylic

Length: 1790mm Width: 900mm


Height: 595mm - 630mm [height adjustable] 190L [200mm below the bath rim] Capacity:


Bath Type: Freestanding spa bath


Waste Position: Centre Net Weight: 85kg

Pump 6102 Voltage 240W 750W Power Heater 700W 7.5A Current Flow Rate 350LPM

## 1790







## **OPTIONAL ACCESSORIES**

- ☑ 40mm Removable pop-up waste Chrome WA001, White Gloss WA002. Black Matte WA003
- ☑ Pop-up waste &overflow kit Chrome OWA001
- ☑ Pop-down waste &overflow kit Chrome OWA002
- ☑ Pop-down waste &overflow kit Black OWA003
- ☑ Sia headrest Black Curved SY242-B

Spa bath pumps must be fitted in accordance with relevant national wiring electrical standards AS3000. The pump is fitted with a standard 10A three pin plug power supply The spa bath pump power connection must be accessible so that it can be switched OFF in case of an emergency, but must not be accessible by the bath user. Use 1 waterproof power point under the bath. Edgetec recommends that the pump be supplied be an isolating transformer or supplied through a residential current device(RCD) with a rated operating current of <30mA. If damage does occur to the power cord it must be replaced by Edgetec or an authorised service agent or suitable qualified person.







